


Poor engine running / jerking / misfiring / power loss – when accelerating after cold start


Gamma-Engine G4FG - 1.6 MPI / Hyundai i30 GDH

VIN: TMAD381BAEJ077701


The following measurement diagrams are from the track below.




14.02.2018




14.02.2018




17.02.2018



17.02.2018



17.02.2018
(2. measurement)



17.02.2018
(2. measurement)

